

FIG. 1






FIG. 2




000270" E2082960

FIG. 3



008220" E2082960

FIG. 4



008220" E2082960

FIG. 5




FIG. 6




FIG. 7




FIG. 8






FIG. 9



003220" E2032950

FIG. 10



10/27

FIG. 11

WARNINIG

IT IS PROHIBITED BY LAW TO COPY
IMAGE WHICH IS BEING READ.

READING OPERATION IS INTERRUPTED.

FIG. 13

WARNINIG

IT IS PROHIBITED BY LAW TO OUTPUT
IMAGE WHICH IS BEING PRINTED.

PRINTING OPERATION IS INTERRUPTED.

008220" E2082960

FIG. 12




FIG. 14




FIG. 15

SCANNER	SPECIFIC IMAGE 1	JAPANESE YEN BANK BILL
	SPECIFIC IMAGE 2	AMERICAN DOLLAR BANK BILL
PRINTER	SPECIFIC IMAGE 3	DEUTSCH MARK BANK BILL
	SPECIFIC IMAGE 4	BRITISH POUND BANK BILL


FIG. 17

FIG. 16




FIG. 18




FIG. 19




FIG. 20A





FIG. 20B

FIG. 21




FIG. 22




FIG. 23




FIG. 24






FIG. 25A



008220" E2082960

FIG. 25B



009270" 22082560

FIG. 26




FIG. 27




FIG. 28

